


Quick Operation Guide

While holding down the [METRONOME ON/OFF] button, press the highlighted keys shown below to set parameters. (Refer to the diagram **3** below.)

While holding down the [DEMO] button, press and hold the [METRONOME ON/OFF] button, then press the highlighted keys shown below to set parameters. (Refer to the diagram **4** below.)

3



4

