

Dante Accelerator Driver V2.0.0 for Mac Release Notes

Caution

- You need to update the Dante Accelerator Firmware to V2.0.0.

V1.0.1 to V2.0.0

Specification Changes

- Now supports Dante Redundancy. (The secondary port became available.)
- Changed the system requirements to the following.
OS X 10.7.5 or 10.8.x

Fixed Bug

- Solved the problem in which the Dante Accelerator for which Pull up/Pull down is set to enable does not work properly in OS X 10.8.

Known Issue

- None.

Update History

V1.0.0 to V1.0.1

Specification Changes

- Disabled the Pull up/Pull down settings in OS X 10.8 which do not support Pull up/Pull down.

Fixed Bug

- Solved the problem in which the audio sound would not play back properly when two audio applications were simultaneously using Dante Accelerator.

Known Issue

- If the buffer size is set to 2048 when the audio buses in the VST Connections of Nuendo are set to less than 32 channels in OS X 10.6.8, continual noise may occur. Set the value to something other than 2048.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2013-2014 Yamaha Corporation.

Dante Accelerator Driver V2.0.0 for Mac リリースノート

注意

- ・ Dante Accelerator Firmware を V2.0.0 にアップデートしてお使いください。

V1.0.1 → V2.0.0

仕様変更

- Dante リダダンシーに対応しました。(セカンダリーポートが使用可能になりました。)
- 動作環境を変更しました。以下の環境が必要です。

OS X 10.7.5 または 10.8.x

修正した不具合

- Pull up/Pull down 設定された Dante Accelerator を、OS X 10.8 にインストールすると正常に動作しない問題を修正しました。

既知の不具合

- なし

過去のアップデート内容

V1.0.0 → V1.0.1

仕様変更

- OS X 10.8 では Pull up/Pull down をサポートしていないため設定を無効にしました。

修正した不具合

- Dante Accelerator を 2 つのオーディオアプリケーションで同時に使用したときに、音が正常に再生されない問題を修正しました。

既知の不具合

- OS X 10.6.8 で、Nuendo の VST コネクションのオーディオバスを 32 チャンネル以下に設定した状態でバッファーサイズを 2048 にすると、継続的にノイズが出力されることがあります。2048 以外の値を設定してください。

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。

(C) 2013-2014 Yamaha Corporation.